

SAFETY ALERT

Dropped Bottom Hole Assembly Strikes Worker

Safety Alert: #07 - 2010	Release Date: May 11, 2010
Incident Type: Dropped object from slipped sling	Country of Origin: Western Canada

Description of Incident:

- A service rig crew had removed a full tubing joint from the Bottom Hole Assembly (BHA) with tongs. The BHA was standing with one end resting on ground, through the rig floor beside the BOP's.
- The rig manager, driller, derrickhand and floorhand #1, conducted a hazard assessment and tailgate meeting on the rig floor. Due to the height of the BHA, they made a decision to pick up the BHA (5.5 M long and 404 lbs) with a nylon sling and lay down on the catwalk to install a handling pup.
- The rig manager used a double choked nylon sling on the BHA. When raising the BHA to floor height, the derrickhand positioned the BHA over the V-Door. While positioning BHA, Floorhand #2 entered from the off driller side (where V-Door was positioned). When hearing the rig manager tell everyone to stand clear, floorhand #2 turns to leave the floor, the BHA suddenly fell from the sling, contacting the worker with a glancing blow to the right arm.

What Caused It:

- Pick-up nubbin not used to lift BHA, instead a nylon sling was used on the smooth surface of the pipe with no means of preventing it from sliding off.
- Work area congestion around suspended BHA.
- Worker joined work task while lift was in progress.

Corrective Actions:

- Rigs should be equipped with enough pick-up nubbins to safely lift any sized BHA onsite and be used for all lifting activities of BHAs.
- Rigging and Slinging, and/or Hoisting and lifting procedures should include the types of lifts and methods for using nylon slings.
- Workers should only join a work process after being specifically instructed to do so, so others are aware of them.
- All personnel to be involved in a work process should be involved in the field level hazard assessment.

Contact:

For more information of event, please contact safety@enform.ca

DISCLAIMER:

This Safety Alert is designed to prevent similar incidents by communicating the information at the earliest possible opportunity. Accordingly, the information may change over time. It may be necessary to obtain updates from the source before relying upon the accuracy of the information contained herein. This material is presented for information purposes only. Managers and supervisors should evaluate this information to determine if it can be applied to their own situations and practices.

1538 – 25th Avenue NE Calgary, Alberta, Canada T2E 8Y3 www.enform.ca Telephone 403 250-9606