

Silica Dust:

It will take your breath away



Enform's Exposure Control Plan (ECP)
October 8, 2015



Outline

- What is silica?
- Why should I care?
- Exposure risk
- Exposure control
- Enform's approach

Questions?



What is silica

 Silica is naturally occurring and can be found everywhere (SiO₂)

Silica can be crystalline (quartz) or non-crystalline

(amorphous)

Crystalline silica can be found in:

- Rock
- Sand
- Products like cement, etc.



Why should I care?

- Silica is a hazard (primarily chronic) when it is breathed deep into the lungs (respirable)
- Silica causes the following illnesses:
 - Silicosis lung scar tissue
 - Lung cancer
 - Bronchitis
 - Kidney disease
- Irreversible and progressive



Exposure risk

- Silica's OEL
 - 8-hour TWA
 - What does that mean?
 - 2X lower than lead (0.05 mg/m3)

- 400X lower than nuisance dust (10 mg/m3)
- If it's silica and it's visible, overexposure is just a matter of time!



Exposure risk

How do we re-think our perceptions of risk?



Exposure risk

- You may be thinking that I am exposed for only a few days, weeks or months, I will be ok, right?
- A worker at 100X the Silica OEL

- With no respirator they get a working lifetime in 90 days
 - Even at 100X, acute health effects may not provide adequate warning
 - After 100X, risks are likely not linear,
 - i.e. high exposures for even short periods have more risk

Where could I be exposed?







Frack

Proppant
Handling and
Storage

Seismic

Air-hammer Drilling

Drilling

Drilling Mud Additives

Fracking - Exposure Sources

- Proppant (sand: 30-99% quartz)
 - The high percentage of quartz and amount of energy imparted into the sand makes this hazard unique
 - Any transfer points
 - Rail to truck
 - Truck to sand tent or site sand storage (vertical or horizontal)
 - Site sand storage to hopper
 - Pneumatic in-loading on site
 - Working in visible frack dust?



Drilling - Exposure Sources

- Handling and adding drilling mud dry-product additives
 - Barites, Graphite, etc...
 - If it's naturally sourced, be suspicious
- Cement In-loading
 - Portland cement verses additives
- Cuttings Dryers
 - Most of cuttings are rock = silica
- Shaker Mist
 - Rock dust and fluid additives





Photo: Eelgin Industries

Seismic - Exposure Sources

- Main source is hard rock such as sandstone, granite and shale
 - Depends on shot hole parameters

- Depth and diameter of hole
- Wet or Dry Environment
 - Up on hill or next to river

Other Sources

- Refractory brick removal furnaces*
- Construction road and lease
- Abrasive blasting sand substitutes*
- Cement handling
- Cutting, grinding, and drilling concrete



Controls - Engineering

 The answer to many silica exposures is engineering and administrative controls

This does not have to be expensive/difficult

- Wet materials
- Distance/time etc.



Take some action (action = caring)



Controls - PPE

- Different dust levels = different protection levels
 - Respirator protection factors
 - Half-face 10
 - Full-face 50 and 100
 - PAPR or Supply Air 1,000

- Why? Leakage, where the respirator meets the face
- Coveralls



- Fracking
 - Depends on the presence of engineering controls and where you are working
 - What is needed?
 - Consistently applied engineering controls



- Fracking
 - Some workers need a ½ mask
 - Not in dust on an on-going basis
 - At least 3 meters from source
 - Some workers need full-face or better
 - On-going and close to source
 - Handling frack dust (powders)
 - Adjacent workers may be at risk

 If you are breathing visible frack dust you need a respirator (micro-seismic, flow back, medics etc.)



- Drilling Dry-Product Additive Handling
 - Use engineering ventilation controls
 - Direct exhaust ventilation into mud tanks
 - Add product slowly one bag per minute
 - Reduces dust generation (energy)
 - Ensures complete incorporation into drilling fluid
 - Wear a respirator (minimum half mask)
 - Keep your distance from cement in-loading and use a dust capture bag on exhaust
 - Follow Invert exposure control plan



- Air-hammer Drilling
 - Engineering controls
 - Venturi
 - Vacuum
 - Water injection
 - Blower fan
 - Stay upwind of dust when ever possible

>>>>>>>>>

- Use respirator
 - No engineering controls? You may need a full-face respirator



Enform's Approach

- Silica ECP template
 - Modular approach
- Guidance Sheets
 - Sources
 - Controls
 - Hazard Assessment



conduct regular exposure measurements to ensure controls are working. If the work situation occurs 30 or more Tier 0 - No respiratory protection required (Includes standard controls such as signs and training on the hazards of silica)

days in a calendar year, implement periodic health surveillance.

Applies on work site (check all that apply)	Tier 0 (<0.0125 mg/m³)	Other control considerations	Monitoring data collected?
п	At least 10 meters from any emission sources, not present in visible frack dust at any time and if pneumatic in-loading is being conducted engineering controls are in use such as dust suppressants, ventilation, etc.		п
	Personnel inside cab of blender that is positively pressurized with HEPA-filtered heated/cooled air and with air-tight doors and windows that remain closed	Half-face respirator required to exit cab provided you remain 3 meters from sources	

Tier 1 - Half-face respirator with P100 filters (Includes standard controls such as signs, training on respirators and silica. Medically cleared to wear a respirator and fit tested)

Applies on work site (check all that apply)	Tier I (0.0125 - <0.125 mg/m²)	Other control considerations	Monitoring data collected?
	Hopper attendant on frack site or sand tent where proppant is dumped from an end dump truck directly into hopper		
	At least 3 meters from any emission sources and present in visible frack dust occasionally	Use engineering controls, as adjacent personnel on site may be at risk of overexposure	
	Personnel inside cab of blender that is <u>NOT</u> positively pressurized with HEPA-filtered heated/cooled air and with air-tight doors or when dust suppressant not in use	Half-face respirator required to exit cab	
	Trucking personnel conducting loading or unloading	Consider keeping truckers restricted to cab of truck for conveyor or auger loading/unloading	
	Personnel within 1-3 meters of hopper or conveyor junctions with dust suppressant or ceramic proppant in use	Keep personnel at least 1 meter away from edge of source equipment to manage excursion limits	
	Personnel within 3 meters of Vertical Sand Storage discharged directly into Hopper with dust suppressant or ceramic proppant in use		
	Personnel handling used silica-contaminated coveralls or HEPA vacuuming contaminated buildings etc.	Vacuum must be HEPA- filtered, consider wetting coveralls prior to handling	

the associated controls. For Tier I or higher work situations, evaluate how often the work situation occurs and



What Now?

- Silica ECP and Guidance sheets (frack) available at enform.ca
- Worker tools and resources are being completed
- The <u>CCH Guideline</u> update for release later this year
- Pick up the Fall issue of Frontline



Summary


- Silica is not nuisance dust!
- Silica is everywhere
- What you don't know will still hurt you
- Enform's Controlling Chemical Hazards Guideline has the answers you need
- Solutions by industry for industry



Is your worker's future clear?

Healthy Lung

Silicosis Lung





Questions

Contact: Robert Waterhouse

Email: robert.waterhouse@enform.ca

