

Safety Alert

Issue # 02-2026


ENERGY
SAFETY
CANADA

Sideboom Powerline Strike Potentially Serious Incident

What Happened?

A tracked sideboom was in the process of relocating three lengths of pipe on a rural road. Three overhead powerlines were in the path, two of which were identified as the task began. After successfully crossing the first line, the boom contacted a second line that was not identified and parted an energized 25kV powerline.

No injuries occurred; this incident was considered to have a serious injury or fatality (SIF) potential due to the presence of electrical energy.



Why Did it Happen?

- Due to conditions, the contractor's supervisor moved the pipelayer from the right-of-way and designated travel path to the public roadway.
- The change in route bypassed physical barriers intended to prevent overhead line contact.

- The Field Level Hazard Assessment (FLHA) conducted prior to beginning work was not fully complete.
- An updated FLHA was not completed when the work scope changed; the FLHA did not account for hazards of alternate routes.
- It was not identified that the change in route resulted in physical controls intended to prevent overhead line contact being absent.
- Two of three overhead lines were identified; however, the walkdown of the new route was not complete, resulting in one line being missed.
- Cloudy conditions resulted in overhead lines blending with skyline.
- The supervisor and sideboom operator were not adequately trained for their respective roles.

What Did They Learn?

- Engage with contractors to understand their supervisor competency programs.
- Verification of training and competency assessments are required for contract supervisors.
- The contractor's Construction Kick-off checklist was updated to include a requirement for the site supervisor to validate competency of their crews.
- Understand how site supervisors handle changes from planned work (i.e., Work as Imagined vs Work as Done).
- Revise how written programs address controlled and uncontrolled overhead line crossings.

Safety Alert

Issue # 02-2026

ENERGY
SAFETY
CANADA

Ask Yourself and Your Crew:

- Could a similar incident happen at your site?
- How do we respond when scope shifts, even when perceived risk is low?
- Do we have a clear process for re-assessing risk when plans change?

Industry Resources

- Training | [Powerline Safety Awareness Online Course](#)
- Report | [Potentially Serious Incidents Summary 2019-2024 Data](#)

Submit Your Safety Alert

Help industry by sharing lessons learned from an incident. [Submit your Safety Alert.](#)

Share and Collaborate

Energy Safety Canada (ESC) works collaboratively with industry to share information aimed at helping companies of all sizes improve safe work performance.

Disclaimer

Use of this document or any information contained herein is at the user's sole risk. ESC makes no representations and assumes no liability. For further information on these restrictions, go to <https://www.energysafetycanada.com/Legal>

Copyright/Right to Reproduce

Copyright for this document is held by Energy Safety Canada, 2026. All rights reserved. Energy Safety Canada encourages the copying, reproduction and distribution of this document to promote health and safety in the workplace, if Energy Safety Canada is acknowledged. However, no part of this publication may be copied, reproduced or distributed for profit or other commercial enterprise, nor may any part be incorporated into any other publication, without written permission of Energy Safety Canada.