

SAFETY ALERT

Workers Hand Partially Amputated From Contact With Fan Blade

Safety Alert: #08 - 2010	Release Date: May 18, 2010
Incident Type: Rotating equipment injured worker	Country of Origin: Western Canada

Description of Incident:

- A maintenance worker was performing routine housekeeping activities in a generator building. As the worker was cleaning the building walls, he noticed a small amount of oil below the generator fan guard.
- The worker folded a small rag and attempted to clean the area, while the generator was running. A small opening on the fan guard, which allows for removal of the guarding during servicing, allowed the rotating fan blades to grab the rag, which pulled the workers hand into fan blades.
- This resulted in a partial amputation of the workers hand.

What Caused it:

- Rotating equipment guard did not completely mitigate the rotating hazard allowing contact with the worker when not isolating the equipment
- Hazard of loose rag being drawn into rotating fan not recognized
- Failure to follow procedures administrative control requires equipment to be isolated prior to servicing

Corrective Actions:

- Evaluate rotating equipment has complete guarding to prevent access. If inadequate, consider implementation of administrative controls. Procedures for working on or near rotating equipment to also include hazard assessment of inadequate guarded equipment.
- Work with rotary equipment suppliers to ensure adequate guarding in place prior to installation or constructed prior to start up.
- Evaluate the need for isolation procedures to ensure equipment is isolated and de-energized prior to attempting any housekeeping tasks on running equipment.

Contact:

For more information of event, please contact safety@enform.ca

DISCLAIMER:

This Safety Alert is designed to prevent similar incidents by communicating the information at the earliest possible opportunity. Accordingly, the information may change over time. It may be necessary to obtain updates from the source before relying upon the accuracy of the information contained herein. This material is presented for information purposes only. Managers and supervisors should evaluate this information to determine if it can be applied to their own situations and practices.